

From: [Blaze, Stephen](#)
To: [Mickunas, Dave](#); [Powell, Greg](#)
Cc: [Moore, Gary](#); [Singhvi, Raj](#)
Subject: RE: F.J. Doyle Salvage Site
Date: Monday, October 01, 2018 1:54:30 PM

The only way to prove the existence or absence of dioxin would be by sampling and subsequent analysis.

But my questions would be.... who is the end user of the dioxin data and what statutes are they trying to meet? Is this for a disposal requirement?

Each State has different requirements.

What would be your quantitation limit for dioxin to make a decision on changing the way you will dispose of the demolition waste?

Basically what would be the data quality objective of the dioxin data and what would be the "if than" decision statement if you had a positive above "what" level.

If you set your detection level low enough, you will find dioxin everywhere that smoke has traveled. So it is important to analyze to the correct reporting limit.

From: Mickunas, Dave
Sent: Monday, October 01, 2018 1:35 PM
To: Powell, Greg <Powell.Greg@epa.gov>
Cc: Moore, Gary <Moore.Gary@epa.gov>; Singhvi, Raj <Singhvi.Raj@epa.gov>; Blaze, Stephen <Blaze.Stephen@epa.gov>
Subject: Re: F.J. Doyle Salvage Site

To do due diligence, I think that you would want to analyze for dioxin.

Sent from my iPhone

On Oct 1, 2018, at 9:08 AM, Powell, Greg <Powell.Greg@epa.gov> wrote:

If you look for them you will probably find some of the isomers of dioxin. I'll forward to our chemists.

Steve ,Dave and Raj any input?

Greg Powell
USEPA-ERT
Erlanger, KY Office
(859)594-6549 office
(513)607-1572 cell

"Facts do not cease to exist because they are ignored."

From: Moore, Gary

Sent: Monday, October 01, 2018 11:47 AM

To: Powell, Greg <Powell.Greg@epa.gov>

Subject: F.J. Doyle Salvage Stie

Greg:

Can you get this to the right person if not you?

We are going to be demolishing a building at a former PCB dismantling facility. They did do cutting and grinding on the transformers. It is a metal building with wood structures.

We are going to do the following: Asbestos Inspection – Required for Reno/Demo

We are planning on doing PCB wipe samples to include analysis for Aroclor 1268 (Galbestos?)

We are going to sample for lead paint

Question: Is there a need to include Dioxins/Furans for the wipe samples?

Thanks

Gary W. Moore (6SF-ER)

Federal On-Scene Coordinator

U.S EPA Region 6

1445 Ross Ave, Suite 1200

Dallas, TX 75202-2733

Cell: 214.789.1627

moore.gary@epa.gov